JLab-FNAL-SLAC LCLS-II Cryomodule Shipping and Receiving Meeting

JLab Action Items

Unloading Procedure

- Assist counterparts in FNAL and SLAC in developing a procedure for unloading the cryomodules in Sector 10 at SLAC.
- Participate in developing requirements for improvements to be made to Sector 10 unloading area

Readiness Timeline

 Identify a set time by which shipping equipment and infrastructure upgrades need to be ready in order to meet prototype cryomodule schedule

Review FNAL Analysis

Review FNAL analyses on Shipping Frame, End Caps and Shipping Loads (when completed)

JLab Loading Procedure

 Prepare and distribute loading procedure used at JLab for loading Cryomodules on to flat-bed trucks

Procurement Timeline

- Determine timeline for shipping frame and end cap procurement
- Specify design review dates and aims